

CITY OF TAMPA
COMMUNITY DEVELOPMENT BLOCK GRANT
COMMUNITY NEEDS AND RECOMMENDATIONS FY2004-2005
December 28, 2004

Block Club: Area V

Neighborhoods: Parkview, Courier City/Oscawana, North Hyde Park, Old Hyde Park, Historic Hyde Park, New Suburb Beautiful, Bayshore Gardens, and Palma Ceia Park.

Boundaries: I-75 (north); Euclid Avenue (south); Bayshore Blvd. (east); MacDill Avenue (west).

Contact Person: Mr. Robert L. Allen, Chairperson
301 N. Fremont Avenue
Tampa, FL 33606
Phone: 254-6844 (h)

Need and Recommendation 2. Street Resurfacing and *Repair Stormwater Run-off on N. Fremont Avenue.*

We strongly recommend that the City of Tampa Wastewater Department, and Transportation Division, address the street resurfacing and *stormwater run-off* situation at N. Fremont Avenue (between W. Cypress St. and W. Cass Street). W. Cass Street is in dire need of resurfacing (paving) and *stormwater sewage* attention.

When traveling along N. Fremont Avenue, one has to be careful of a possible head-on collision. The street is in the worst condition between W. Cypress Avenue and W. Cass Street. Due to the deep potholes, there is also danger of damaging your vehicle while driving on N. Fremont Avenue at W. Cypress (south direction), and while driving on N. Fremont Avenue at W. Cass Street.

Response: The Stormwater Department will respond in the Non-Eligible Community Needs.

Response: From Scott Shaw, Traffic Operations Chief, Department of Public Works, Operations Division, 622-1955. West Cass Street between N. Boulevard and N. Howard was paved in 1997 and is in good condition. North Fremont Avenue from Cypress Street to Laurel Street needs resurfacing and will be placed on a clearance list for future paving. Wastewater Department needs to repair their facilities before paving.

Response: From Charlie Lynch, Wastewater Planning and Maintenance Management Supervisor, Wastewater Department, 274-8916. The Wastewater Department has facilities in the areas listed

and has performed field investigations at the locations where attention has been requested. Based on our initial investigation, there are roadway depressions in these areas that may be a result of deficiencies with the existing wastewater pipelines. The Department will be conducting an extensive television inspection of these pipelines to determine the condition of the pipe. If deficiencies are found, the pipelines will be repaired. We will coordinate any repairs that may be required with the Department of Public Works.

Update: From Charlie Lynch, Wastewater Planning and Maintenance Management Supervisor, Wastewater Department, 274-8916. The Wastewater Department has completed the television inspection of the pipeline along N. Fremont Avenue. The inspection showed that the pipeline had some minor deficiencies that can be repaired by lining the pipe and a small section under Cypress Street that requires replacement. The Department is currently preparing plans and will schedule the work for FY05. The repairs will be coordinated with the Department of Public Works.